

IN THE WRITTEN DESCRIPTION

Please replace the paragraph at page 7, lines 1-13 of the specification as filed (which corresponds to paragraph [0027] of the published application, US 20060186064) with the following replacement paragraph:

As shown in FIG. 4, at least one second extension 19 extends downward from base 3 and includes horizontal portion 19a which goes into substantially horizontal slot 21 associated with mounting member 7. Slot 21 receives extension 19a as divider 2 and base 3 are slid forward to be locked into place on mounting member 7. A-shaped lip 12 resides in recess 17 during the placement of divider 2 and base 3 in position on mounting member 7. As divider 2 and base 3 are moved to the front of the shelf (i.e. to the left in FIG. 4), the surface 12a of A-shaped lip 12 comes into physical contact with surfaces 18a of flanges 18 which are part of base 3. A corresponding flange 18 with a surface 18a on the back side of base 3 is just barely visible in the perspective view of FIG. 4. This other surface 18a (~~not numbered in FIG. 4 to avoid drawing clutter but shown and numbered in FIG. 7~~) also contacts surface 12a of lip 12. The two surfaces 18a in contact with surface 12a on lip 12 prevent "fishtailing" of, or lateral movement of, divider 2 and base 3 about extension 14 (i.e. about the front portion of the shelf).